

Schedule 6, Part A Notification

Permit Number	PP3238LX
Name of Operator	Hexion UK Ltd
Location of Installation	Sully Moors Road, Barry, Vale of Glamorgan
Time and date of detection	22 nd November 2016 (initial notification by telephone on this date)

(a) Notification requirements for any malfunction, breakdown or failure of equipment or techniques, accident, or fugitive emission which has caused, is causing or may cause significant pollution

To be notified within 24 hours of detection

Date and time of the event	
Reference or description of the location of the event	
Description of where any release into the environment took place	
Substance(s) potentially released	
Best estimate of the quantity or rate of release of substances	
Measures taken or intended to be taken to stop any emission	
Description of the failure or accident	

(b) Notification requirements for the breach of a limit

To be notified within 24 hours of detection unless otherwise specified below

Emission point reference / source	No 2 Boiler Stack (A1)
Parameter(s)	Carbon Monoxide (CO)
Limit	140 mg/m ³
Measured value and uncertainty	>602 mg/m ³ – e-mail notification only, full report not available – this will contain the uncertainty
Date and time of monitoring	8 th November (the time of monitoring will be in the full report)
Measures taken or intended to be taken to stop the emission	Specialist service company attended site on the 9 th November to fix fault. They reported: <i>Analysed combustion, CO found to be high at low-fire. Checked inside gas servo-motor and found feedback potentiometer to be loose causing inaccurate control of the valve. Remedied, then checked and modified positions as required. Printed out combustion results and handed to site. All OK upon leaving.</i>


Time periods for notification following detection of a breach of a limit	
Parameter	Notification period

(c) Notification requirements for the detection of any significant adverse environmental effect	
To be notified within 24 hours of detection	
Description of where the effect on the environment was detected	
Substance(s) detected	
Concentrations of substances detected	
Date of monitoring / sampling	

Schedule 6, Part B Notification

Part B – to be submitted as soon as practicable

Any more accurate information on the matters for notification under Part A.	As per Part A
Measures taken, or intended to be taken to prevent a recurrence of the incident	Specialist service company attended site on the 9 th November
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has or may be caused by the emission	Specialist service company detected a problem as detailed above, fixed it and measured gas concentrations as acceptable.
The dates of any unauthorised emissions from the installation in the preceding 24 months.	N/A

Name*	Paul Meakin
Post	Site Leader
Signature	
Date	23 rd November 2016

* authorised to sign on behalf of Hexion UK Ltd.