

Feb 2022

Day	Downtime	Availability	Daily Mwh	Rationale
1	0	100.00%	320	
2	0	100.00%	327	
3	0	100.00%	324	
4	0	100.00%	320	
5	0	100.00%	320	
6	0	100.00%	312	Lost CBISS CEMS data at 0600
7	0	100.00%	313	
8	1.5	93.75%	285	Plant Trip due to PLC CPU stopped
9	0	100.00%	312	
10	0	100.00%	314	
11	7	70.83%	213	Boiler PLC tripped due to installation of Cbiss kit
12	0	100.00%	316	
13	0	100.00%	313	
14	0	100.00%	317	
15	0	100.00%	317	
16	0	100.00%	311	
17	0	100.00%	297	Cbiss Resumed operation
18	0	100.00%	318	
19	0	100.00%	329	
20	0	100.00%	300	
21	0	100.00%	262	Load drop due to disk screen blockage
22	0	100.00%	319	
23	0	100.00%	321	
24	13	45.83%	122	Boiler trip on High live steam temperature, found SH spray #1 valve not controlling.
25	7	70.83%	173	Procured replaced Valve positioner and recommissioned .
26	0	100.00%	309	
27	0	100.00%	321	
28	20.5	14.58%	6	Chain Conveyor 3 jammed due to sheared wear strip becoming lodged in link
Month	49	92.71%	8011	