


Schedule 5 – Notification

Part A

Permit Number	EPR/BP 3635MR
Name of operator	Harsco Environmental
Location of Facility	Harsco Ring Fenced Site Tata Steel Port Talbot
Date reported	25/07/23

Date and time of incident	13 th & 14 th April
Location	Lancing Booth
Substance released	No release of particulates during the 2-day period of no data recorded
Measures taken or intended to be taken to stop any emission	Regular monitoring of data to be carried out in line with the operational hours of the lancing booth.
Description of the failure or accident	A loss of stack monitoring data occurred during the migration of data from a previous employee's laptop to the current EHS Manager. Did not identify the missing data at the time of reporting the quarter 2 stack results for the lancing booth.

Name	Paul Morgan
Post	EHS Manager
Signature	
Date	25/07/23