


Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	10/08/2023 09:23 Unplanned

(PART A)	
Reference or description of the location of the event	A56 Minister Stein Morfa Coke Ovens Hood
Reason for the outage	339 x ovens pushed off the hood between 09:23 10/08/2023 – 15:39 15/08/2023. No. 1 Guide could not be used on the hood as there was damage to the hood structure platform which connects the guide and hood. There was also a hood communications fault. No 3 Guide was unavailable as the cage was being changed (planned).
Immediate action taken to mitigate environment incident (if applicable)	
Has the abatement equipment been reinstated? (If yes state date and time)	Yes
If no confirm planned date to reinstate abatement equipment	
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	No
Reference	A56 MCO 107_100823
(PART B) Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	
Date abatement equipment returned to service	15/08/2023
Name	Nicola Parnell
Post	Environment Lead - UK ETS & Air Quality
Signature	
Date	16/08/2023
Reference	A56 MCO 107_100823

