


Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	23/08/2023 @ 22:56 Unplanned

(PART A)	
Reference or description of the location of the event	A10 Fan 3 Fume Extraction
Reason for the outage	Unplanned outage due to high emissions
Immediate action taken to mitigate environment incident (if applicable)	
Has the abatement equipment been reinstated? (If yes state date and time)	Yes 24/08/2023 @ 07:48
If no confirm planned date to reinstate abatement equipment	
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	No
Reference	A10 BOS 113_230823
(PART B) Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	N/A
Date abatement equipment returned to service	
Name	Nicola Parnell
Post	Environment Lead, UK ETS & Air Quality
Signature	
Date	27/08/2023
Reference	A10 BOS 113_230823