

Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	05/09/2023 @ 08:50 Planned Maintenance

(PART A)	
Reference or description of the location of the event	A16 Fan 6 fume extraction
Reason for the outage	Planned maintenance – Scheduled inspections on impeller & casing
Immediate action taken to mitigate environment incident (if applicable)	Fans 4 and 5 remain in operation
Has the abatement equipment been reinstated? (If yes state date and time)	No
If no confirm planned date to reinstate abatement equipment	08/09/2023
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	Yes
Reference	A16 BOS 118_050923
(PART B) Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	N/A
Date abatement equipment returned to service	
Name	Nicola Parnell
Post	Environment Lead, Air Quality & UK ETS
Signature	
Date	05/09/2023
Reference	A16 BOS 118_050923