


Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	18/09/2023 13:14 Planned Maintenance

(PART A)	
Reference or description of the location of the event	A15 Fan 5 fume extraction
Reason for the outage	Planned maintenance – deep cleaning
Immediate action taken to mitigate environment incident (if applicable)	Fans 4 and 6 remain in operation
Has the abatement equipment been reinstated? (If yes state date and time)	Yes 19/09/2023 @ 10:44
If no confirm planned date to reinstate abatement equipment	
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	No
Reference	A15 BOS 122_180923
(PART B) Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	N/A
Date abatement equipment returned to service	19/09/2023
Name	Nicola Parnell
Post	Environment Lead, Air Quality & UK ETS
Signature	
Date	19/09/2023
Reference	A15 BOS 122_180923