

**Sep 2023**

Day	Downtime	Availability	Rationale
1	0	100.00%	
2	4	83.33%	Plant trip due to PLC analogue card fault
3	5	79.17%	Plant restart, high ambient temperatures causing vacuum issues
4	0	100.00%	
5	0	100.00%	
6	0	100.00%	
7	0	100.00%	
8	0	100.00%	
9	0	100.00%	
10	0	100.00%	
11	0	100.00%	
12	0	100.00%	
13	0	100.00%	
14	0	100.00%	
15	4.5	81.25%	Plant trip due to Feed water valve fault
16	0	100.00%	
17	0	100.00%	
18	1.5	93.75%	Chain Conveyor tripped, load reduced, turbine tripped on vibration due to low load
19	0	100.00%	
20	0	100.00%	
21	0	100.00%	
22	0	100.00%	
23	23	4.17%	Plant Annual Shutdown
24	24	0.00%	
25	24	0.00%	
26	24	0.00%	
27	24	0.00%	
28	24	0.00%	
29	24	0.00%	
30	24	0.00%	
<b>Month</b>	<b>206</b>	<b>94.64%</b>	