



DLS Waste Acceptance Flow Chart




Waste Enquiry for Treatment, Disposal or Transportation

Key	
Operator Level	
Manager Level	




REJECT THE WASTE REQUEST.

ACCEPT THE WASTE REQUEST AND SCHEDULE THE COLLECTION OR ACCEPTANCE



RECEIVE THE WASTE FOR AT SITE



PROCEED WITH TREATMENT / BURIAL OPERATIONS

ALL waste acceptance issues, are to be logged in the Site Dairy / Managers Diary, reported to the DLS Environmental Manager, and if required a DLS incident report will be written up and published.

* It is the responsibility of the waste producer to provide a basic characterisation with all the supporting evidence of the characterisation to DLS.

** WAC testing for Haz Landfill. Lagging / Insulation / Refurbishment Wastes / Ceiling Tiles all require MSDS sheets & Asbestos Surveys. Refractory bricks require MSDS sheets and depending on composition, laboratory testing to determine if crystalline structure has changed.

*** It is the responsibility of the waste producer to provide a correct and fully completed season ticket / Waste Transfer Note / Hazardous Waste Consignment Note which suitably covers the requested waste transfer.

**** At the Morfa Landfill, if the waste materials fails waste compliance, DLS must inform the Client Environmental Department and advise they are to inform the Regulator of the WAC failure.