



Biomass building



Stockpile / Bay



Main transfer building



Boiler (under Part B Permit)



Processed wood chip



Wood shredding



Redwither Brook



Drying floor (covered)



PAL wood treatment (inside building / cover)



Scrap metal / WEEE



Unprocessed wood



Quarantine area



Fire hydrant



Penstock



Permit Boundary



Drying skips

1. Wood chip fuel
2. PAL wood
3. Nails (scrap)
4. Plasterboard

5. Glass
6. Sewage screening
7. Card / plastic bales
8. Wood dust