



Mr P. Wright
Team Leader, Industrial Regulation – North & Mid Wales
Natural Resources Wales
Chester Road
Buckley
Flintshire
CH7 3AJ

Hanson Cement
Padeswood Works
Padeswood
Mold
Flintshire CH7 4HB
Tel: 01244 550330
www.hanson.com/uk
david.quick@hanson.biz

23rd October 2015

Dear Mr Wright

Padeswood Works NRW warning letter 5th October 2015

Thank you for your letter. We acknowledge receipt of the letter and accept the contents. We will respond to the actions detailed in the accompanying compliance assessment report in due course, however wish to put on record the following comments:

- Throughout the investigation process Castle Cement Limited cooperated fully with NRW.
- The CAR notes that there were no dust emissions as a result of the ID fan tripping during December.
- The alleged breach of condition 1.1.1 is on the basis that there is the potential for a release as a result of ID fan trips.
- There was no lasting impact of the dust emissions relating to the clinker cooler heat exchanger.
- The heat exchanger will be replaced as part of the shutdown work in January 2016 at a cost of over £400,000.

As you are aware, we are committed to complying with our permit and minimising any adverse effect of our operations on our neighbours and welcome the opportunity to continue to work with you and your officers to this effect.

Yours sincerely,

David Quick

David Quick
Plant Manager

