

RECEIVED

20 JUN 2013



## Schedule 1 – Notification of Abnormal Emission Page 1 of 1

## Part A – 0508

<b>Permit Number</b>	<b>BL9941</b>
<b>Name of Operator</b>	South Caernarfon Creameries Ltd (SCC Ltd)
<b>Location of Installation</b>	Rhydygwystl, Chwilog, Pwllheli, Gwynedd, LL53 6SB
<b>Location of the Emission</b>	W1
<b>Time and date of the Emission</b>	During 24hrs 12/06/13
<b>Fax To:</b>	<b>01244 548805</b>

<b>Substance(s) emitted</b>	<b>Media</b>	<b>Best estimate of the quantity or rate of emission.</b>	<b>Time during which the emission took place</b>
Ortho-phosphate	W1 water	1.85mg/lt	24hrs

<b>Measures taken, or intended to be taken, to stop the emission.</b>	Dosing pipe connection found to be leaking, so insufficient chemical being dosed. Pipe-work repaired.
---	---

<b>* Name:</b>	H G Jones
<b>Post:</b>	Quality Assurance Manager
<b>Signature:</b>	<i>H G Jones</i>
<b>Date:</b>	20-06-13

\* Authorised to sign on behalf of South Caernarfon Creameries Ltd.

OK FOR PUBLIC REGISTER	INITIALS	DATE
	L.C.	26.7.13
COPIED TO PUBLIC REGISTER	JB	EORM