



Gwynedd Drainage Solutions

Unit 1, Bryn Hyfryd, Llangwyllog, Llangefni, Anglesey, LL77 7PX

Tel. no. 01248 750555 / 07919 323436

Directors: Robert Harman / Wayne Evans

www.gwynedddrainage.co.uk

REPORT

2SISTERS FOOD GROUP LTD

Re: Alleged Pollution / Contamination of nearby river

We arrived on site and met with Chris Elmes, and commenced inspection of drains leading to river.

The water was running clear in all manholes, however we observed grey matter at the bottom of three inspection chambers. The manholes led to a large petrol / oil interceptor. At the bottom of the outflow of the interceptor we observed a small amount of grey slurry. We subsequently sucked out all the slurry, jetted and de-scaled to clear.

We then checked all the other interceptors in the top yard, which were working fine and levels were sufficient. As a matter of precaution we emptied and pressure cleaned these, and also manually emptied road gully's of debris. The manholes upstream from the interceptor were also checked and no evidence of grey matter found.

There is no evidence of contamination in the drainage system.

In our professional opinion, the 'pollution' was residue left at the bottom of the large interceptor.

Drainage and Water Main specialists
Emergency on call services 24hours a day

Working in partnership with RH Group (UK) Ltd

ISO 9001 ISO 14001 ISO 18001

Company reg. no.: 7876413

OK FOR PUBLIC REGISTER	INITIALS	DATE
	SL	3/9/13
COPIED TO PUBLIC REGISTER	JB	EORM