


# Schedule 6 - Notification

## Part B - to be submitted as soon as practicable

Permit Number	<b>BR9383ID</b>	Notification Reference	<b>EP_EX_167</b>
Name of operator	<b>Knauf Insulation Ltd</b>		
Location of Facility	<b>Chemistry Lane, Queensferry, Deeside, Flintshire, CH5 2DA</b>		
Time and date of the detection	<b>13<sup>th</sup> September 2016</b>		

Any more accurate information on the matters for notification under Part A.	As referenced on the Part A Notification. The exact date that the roof vent was extended lower is unknown but it is anticipated to have been in place for circa nine years in order to remove heat from the production hall.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	The duct extension was removed on 11th October 2016 during a planned process shutdown, as agreed with NRW.  During the November shutdown, the curing oven was refurbished with new seals to minimise leakage around the blanket.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	It is not possible to calculate emissions from the lowered roof vent due to there being no duct velocity and very limited draw due to the vent ending lower than the roof profile. In addition the duct extension was removed on 11 <sup>th</sup> October 2016, as agreed with NRW.  It is believed that no permanent harm will result from the incident.
The dates of any unauthorised emissions from the facility in the preceding 24 months.	16/09/14, 8-9/10/14, 15/10/14, 11/01/15, 19/03/15, 20/04/15, 19/06/15, 23/07/15, 17/08/15, 29/08/15, 11/09/15, 5-7/10/15, 27/10/15, 02/02/16, 23/02/16, 15/06/16, 27/06/16, 28/06/16, 10/07/16, 15/08/16, 16/08/16.

<b>Name*</b>	C. Keouski
<b>Post</b>	HSE Manager
<b>Signature</b>	
<b>Date</b>	30 <sup>th</sup> December 2016

\* authorised to sign on behalf of Knauf Insulation Ltd