


# Schedule 6 - Notification

## Part B - to be submitted as soon as practicable

Permit Number	BR9383ID	Notification Reference	EP_EX_187
Name of operator	Knauf Insulation Ltd		
Location of Facility	Chemistry Lane, Queensferry, Deeside, Flintshire, CH5 2DA		
Time and date of the detection	Day of 24 <sup>th</sup> October 2017		

Any more accurate information on the matters for notification under Part A.	<p>The validated CO Daily Average was 82.37mg/Nm<sup>3</sup>.</p> <p>There was a problem with one of the oscillators that drives the vibrating pan from which the coke is delivered into the charge recipe. Although the correct weight of coke was going into the batch, it was not being mixed correctly throughout the whole charge, which resulted in higher CO emissions.</p>
Measures taken, or intended to be taken, to prevent a recurrence of the incident	This was rectified on 24/10/17 by replacing the vibrating pan with a new oscillator. In addition, the position of the camera looking at the vibrating pan was adjusted so the hot end can view the whole of the area concerned.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	It is believed that no permanent harm will result from the incident.
The dates of any unauthorised emissions from the facility in the preceding 24 months.	27/10/15, 02/02/16, 23/02/16, 15/06/16, 27/06/16, 28/06/16, 10/07/16, 15/08/16, 16/08/16, 13/09/16, 14/09/16, 25/04/2017, 24/05/17, 07/07/17, 04/08/17, 14-15/08/17, 06/09/17, 14/09/17, 16-20/09/17, 1-3/10/17

Name*	C. Keouski
Post	HSE Manager
Signature	
Date	4 <sup>th</sup> December 2017

\* authorised to sign on behalf of Knauf Insulation Ltd