

| | | | |
|-----------------------------------|---------------|----------|-------------------|
| STERILE TECHNOLOGIES GROUP LTD | FORM | | No / Level: SP6.4 |
| | Date: 1/01/06 | Issue: 1 | Page: 1 of 1 |

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 18:53 on 11/07/2013

Duration of operation: 12 minutes

Reasons for operation: ID fan trip due to overheating causing it to trip on thermal overload, due to the increased outside temperature.

Measures taken to prevent a reoccurrence: Extra ventilation has be put into the ID Fan cabinet.

The plant returned to normal operation at: 20:05 on 11/07/2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 15:42 on 02/08/2013