

| | | | |
|-----------------------------------|---------------|----------|-------------------|
| STERILE TECHNOLOGIES GROUP LTD | FORM | | No / Level: SP6.4 |
| | Date: 1/01/06 | Issue: 1 | Page: 1 of 1 |

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6



Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 16:02 on 27/07/2013

Duration of operation: 2 minutes

Reasons for operation: ID fan trip due to overheating causing it to trip on thermal overload, due to the increased outside temperature.

Measures taken to prevent a reoccurrence: Extra ventilation has be put into the ID Fan cabinet & a Large Industrial Fan has been aquired and is being used, Maintenance have blown through the ID Fan and its Cabinet with compressed air, to increase air flow, Lloyd Morris Electrical are now coming to site, to inspect the ID Fan.

The plant returned to normal operation at: 18:00 on 27/07/2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 13:00 on 28/07/2013

| | INITIALS | DATE |
|---------------------------|----------|---------|
| OK FOR PUBLIC REGISTER | LC | 31.7.13 |
| COPIED TO PUBLIC REGISTER | JB | EDRM |

NATIONAL INCIDENT RECORDING SYSTEM

NOTIFICATION SUMMARY

Event Number: **Date & Time Observed:**
Date & Time Notified: **Response Language:**
Reporter Language:
Feedback Requested:
Reporter Name: **Reporter Type:**
Reporter Address:
Reporter Contact Details:
Location:
Event Details:
Operational Area: **Public Facing Area:**
Place Name: **Event NGR:**
Country: **Event Status:**
Reported To: **Logged By:**
Date & Time Logged:
Passed For Assessment To: **Date & Time Forwarded**

Potential duplicates within 2km reported within past 2 days:

| Event | Reported | Location | NGR | Details |
|----------|------------|--------------|-------------------|---|
| 01140592 | 29/07/2013 | Bowling Bank | SJ 39585 48234 | Dissolved Oxygen alarm received for Bowling Bank LVL , Lower Dee Dissolved oxygen alarm 1 : 59.09% |

NOTE – There may be other potential duplicates