

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION



Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 19:58 on 25/07/2013

Duration of operation: 1 minutes

Reasons for operation: ID fan trip due to overheating causing it to trip on thermal overload, due to the increased outside temperature.

Measures taken to prevent a reoccurrence: Extra ventilation has be put into the ID Fan cabinet & a Large Industrial Fan has been aquired and is being used, Maintenance are carrying out tests looking for faults.

The plant returned to normal operation at: 20:08 on 25/07/2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 10:46 on 25/07/2013

	INITIALS	DATE
OK FOR PUBLIC REGISTER	LC	6.9.13
COPIED TO PUBLIC REGISTER	JB	EDM

NATIONAL INCIDENT RECORDING SYSTEM

NOTIFICATION SUMMARY

Event Number:	01139194	Date & Time Observed:	25/07/2013
Date & Time Notified:	25/07/2013 20:38	Response Language:	English
Reporter Language:	English		
Feedback Requested:	Y		
Reporter Name:	John Davies Polkacrest Ltd	Reporter Type:	Member of Public
Reporter Address:	Marlborough Road Wrexham Industrial Estate WREXHAM Clwyd LL13 9RJ		
Reporter Contact Details:	Work Telephone: 07974 233 104		
Location:	Wrexham Industrial Estate		
Event Details:	SITA Wrexham : Caller reporting that at 19:38 the emergency vent opened for approx 2 seconds then closed due to a fault on Fan.		
Operational Area:	Northern - Welsh	Public Facing Area:	Northern
Place Name:	Wrexham Industrial Estate	Event NGR:	SJ 38605 49750
Country:	Wales	Event Status:	New Notification
Reported To:		Logged By:	Rowan Roberts
Date & Time Logged:	25/07/2013 20:42		
Passed For Assessment To:	Wales - North East EMDO	Date & Time Forwarded	25/07/2013 20:42

Potential duplicates within 2km reported within past 2 days:

Event	Reported	Location	NGR	Details
01139221	25/07/2013	Wrexham Industrial Estate	SJ 38605 49750	SITA Wrexham : Self reporting Emergency vent opening at 21:08 and closing after 15minutes . The plant is not loading at present.
01138658	25/07/2013	Spring Grove	SJ 38845 50780	Report of a sewerabe/abbotaire type smell on Wrexham Ind Est after 5pm every evening. Contact - Mr Imire - 01978