

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6



Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 20:58 on 25/07/2013

Duration of operation: 9 minutes

Reasons for operation: ID fan trip due to overheating causing it to trip on thermal overload, due to the increased outside temperature.

Measures taken to prevent a recurrence: Extra ventilation has be put into the ID Fan cabinet & a Large Industrial Fan has been aquired and is being used, Maintenance have blown through the ID Fan and its Cabinet with compressed air, to try and increase air flow.

The plant returned to normal operation at: 00:14 on 26.07.2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 10:46 on 25/07/2013

	INITIALS	DATE
OK FOR PUBLIC REGISTER	L.C	6.9.13
COPIED TO PUBLIC REGISTER	JB	EDRM

NATIONAL INCIDENT RECORDING SYSTEM

NOTIFICATION SUMMARY

Event Number:	01139221	Date & Time Observed:	25/07/2013
Date & Time Notified:	25/07/2013 21:42	Response Language:	English
Reporter Language:	English		
Feedback Requested:	Y		
Reporter Name:	n/a n/a Polkacrest / Sita	Reporter Type:	Member of Public
Reporter Address:	Marlborough Road Wrexham Industrial Estate WREXHAM Clwyd LL13 9RJ		
Reporter Contact Details:			
Location:	Wrexham Industrial Estate		
Event Details:	SITA Wrexham : Self reporting Emergency vent opening at 21:08 and closing after 15minutes . The plant is not loading at present.		
Operational Area:	Northern - Welsh	Public Facing Area:	Northern
Place Name:	Wrexham Industrial Estate	Event NGR:	SJ 38605 49750
Country:	Wales	Event Status:	New Notification
Reported To:		Logged By:	Rowan Roberts
Date & Time Logged:	25/07/2013 21:46		
Passed For Assessment To:	Wales - North East EMDO	Date & Time Forwarded	25/07/2013 21:46

Potential duplicates within 2km reported within past 2 days:

Event	Reported	Location	NGR	Details
01139194	25/07/2013	Wrexham Industrial Estate	SJ 38605 49750	SITA Wrexham : Caller reporting that at 19:38 the emergency vent opened for approx 2 seconds then closed due to a fault on Fan.
01138658	25/07/2013	Spring Grove	SJ 38845 50780	Report of a sewerabe/abbotaire type smell on Wrexham Ind Est after 5pm every evening. Contact - Mr Imire - 01978