

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

### NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION



Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 18:45 on 19/07/2013

Duration of operation: 2 minutes

Reasons for operation: ID fan trip due to overheating causing it to trip on thermal overload, due to the increased outside temperature.

Measures taken to prevent a reoccurrence: Extra ventilation has be put into the ID Fan cabinet.

The plant returned to normal operation at: 19:10 on 19/07/2013

*Checked with operator.*

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 10:06 on 22/07/2013

	INITIALS	DATE
OK FOR PUBLIC REGISTER	L.C	31.7.13
COPIED TO PUBLIC REGISTER	JB	EDRM