

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

**NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION**

Notification in accordance with PPC permit condition 5.1.1.6



Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 06:56 on 14/02/2014

Duration of operation: 2 minutes

Reasons for operation: Emergency Vent was tripped by a power surge due to ongoing repairs due to bad weather

Measures taken to prevent a reoccurrence: Power surges on the Industrial Estate are uncontrollable in bad weather.

The plant returned to normal operation at: 07:27 on 14/02/14

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 14:00 on 14/02/2014

