

|                                   |               |          |                   |
|-----------------------------------|---------------|----------|-------------------|
| STERILE TECHNOLOGIES<br>GROUP LTD | FORM          |          | No / Level: SP6.4 |
|                                   | Date: 1/01/06 | Issue: 1 | Page: 1 of 1      |

### NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION



Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 16:55 on 06/09/2013

Duration of operation: 5 minutes

Reasons for operation: ID Fan tripped whilst bringing plant back online after shutdown

Measures taken to prevent a reoccurrence: RJW Rewind (Fan Manufactures) have been in to inspect and repair. After their inspection they have increased the air flow through the "Heat Sink" which has decreased the running temperature of the fan greatly.

The plant returned to normal operation at: 18:00 on 06/09/2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at: 12:45 on 09/09/2013

|                           |          |         |
|---------------------------|----------|---------|
|                           | INITIALS | DATE    |
| OK FOR PUBLIC REGISTER    | KC       | 2.10.13 |
| COPIED TO PUBLIC REGISTER | JB       | EDRM    |

## NATIONAL INCIDENT RECORDING SYSTEM

## NOTIFICATION SUMMARY

|                           |   |                       |                  |
|---------------------------|---|-----------------------|------------------|
| Event Number:             | 01157120  | Date & Time Observed: | 06/09/2013       |
| Date & Time Notified:     | 06/09/2013 17:17  | Response Language:    | English          |
| Reporter Language:        | English   |                       |                  |
| Feedback Requested:       | N   |                       |                  |
| Reporter Name:            | P Sweeny Polkacrest Ltd   | Reporter Type:        | Member of Public |
| Reporter Address:         | Marlborough Road<br>Wrexham Industrial Estate<br>WREXHAM<br>Clwyd<br>LL13 9RJ   |                       |                  |
| Reporter Contact Details: | Work Telephone: 07974 233 104   |                       |                  |
| Location:                 | Wrexham Industrial Estate   |                       |                  |
| Event Details:            | Polcocreast - System fault has caused the ID dan to trip. This has allowed the emergency vent to open for 5mins. All systems back working normally. |                       |                  |
| Operational Area:         | Northern - Welsh  | Public Facing Area:   | Northern         |
| Place Name:               | Wrexham Industrial Estate   | Event NGR:            | SJ 38605 49750   |
| Country:                  | Wales   | Event Status:         | New Notification |
| Reported To:              |   | Logged By:            | Huw Rudall       |
| Date & Time Logged:       | 06/09/2013 17:28  |                       |                  |
| Passed For Assessment To: | Steven White  | Date & Time Forwarded | 06/09/2013 17:28 |

Potential duplicates within 2km reported within past 2 days:

| Event | Reported | Location | NGR | Details |
|-------|----------|----------|-----|---------|
|       |          |          |     |         |

NOTE - There may be other potential duplicates