


STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6



Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 20:08 on 05/07/2014

Duration of operation: 180 minutes

Reasons for operation: The Emergency Vent was tripped due to a failure of the air blast cooler. A water pipe burst resulting in a loss of water triggering a safety feature.

Measures taken to prevent a reoccurrence: Inspection and repairs have been carried out and an order has been placed for a new Air Blast Cooler.

The plant returned to normal operation at: 16:15 on 06/07/14

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at: 10:20 on 08/07/2014

	INITIALS	DATE
OK FOR PUBLIC REGISTER	A.C.	29.10.14
OK FOR PLANT REGISTER	JB	EDem