

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION



Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 19:48 on 18/12/2013

Duration of operation: 27 seconds, less than 1 minutes

Reasons for operation: Emergency Vent was tripped by a power cut due to bad weather

Measures taken to prevent a reoccurrence: Power cuts on the Industrial Estate in bad weather are uncontrollable

The plant returned to normal operation at: 20:15 on 18/12/2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 10:25 on 19/12/2013

	INITIALS	DATE
OK FOR PUBLIC REGISTER	LC	7.2.14
COPIED TO PUBLIC REGISTER	JB	EDRM