

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION



Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 17:16 on 02/08/2013

Duration of operation: 6 minutes

Reasons for operation: Fault F33 highlighted as the electrical Invertor tripped out on Thermal overload due cabinet fan being partially covered in dust and not being fully effective during hotter weather.

Measures taken to prevent a reoccurrence: Fan blades and cowelling cleaned to allow full ventilation into the cabinet.

The plant returned to normal operation at: 17:22 on 02/08/2013

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at : 13:57 on 06/08/2013

	INITIALS	DATE
OK FOR PUBLIC REGISTER	LC	6.9.13
COPIED TO PUBLIC REGISTER	JB	EDRM