

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION



Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 19:40 on 02/10/2014

Duration of operation: 65 minutes

Reasons for operation: The Emergency Vent was tripped due to a power surge which caused the ID Fan to trip triggering a safety feature.

Measures taken to prevent a reoccurrence: Inspections have been carried out and normal operations have resumed..

The plant returned to normal operation at: 20:45 on 02/10/14

The loading of waste ceased while the emergency relief vent was open.

Notified by: Alan Gartside

Position: Senior Plant Manager

Notification completed at: 12:20 on 03/10/2014

OPER FOR PUBLIC REGISTER	INITIALS	DATE
	L.C.	29.10.14
CHECKED BY PUBLIC REGISTER	JB	EDRM