

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 23:15 on 06/01/2015

Duration of operation: 60 minutes

Reasons for operation: The Emergency Vent was tripped due to a power surge which caused the ID Fan to trip triggering a safety feature.

Measures taken to prevent a reoccurrence: Inspections have been carried out and normal operations have resumed..

The plant returned to normal operation at: 00:15 on 07/01/2015

The loading of waste ceased while the emergency relief vent was open.

Notified by: Paul Phillips

Position: Assistant Plant Manager

Notification completed at : 12:20 on 06/01/2015