

STERILE TECHNOLOGIES GROUP LTD	FORM		No / Level: SP6.4
	Date: 1/01/06	Issue: 1	Page: 1 of 1

### NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6

Permit number: WP3836ZF

Name of operator: SITA Wrexham

Location of installation: Marlborough Rd, Wrexham

Location of emission: Release Point A2 – Incinerator Emergency Relief Vent

The emergency relief vent opened at: 07:35 on 27/03/2015

Duration of operation: 240 minutes

Reasons for operation: ID fan belt failure resulting in Emergency Vent opening.

Measures taken to prevent a reoccurrence: New belts fitted and belt tension checked.

The plant returned to normal operation at: 12:50hrs on 27/03/2015

The loading of waste ceased while the emergency relief vent was open.

Notified by: Paul Phillips

Position: Assistant Plant Manager

Notification completed at : 13:10 on 27/03/2015