

Schedule 1 • Notification of abnormal emissions

Part A

Permit Number		EPR/WP3836ZF	
Name of Operator		Tradebe Healthcare National Ltd	
Location of Installation		Wrexham Clinical Waste Incinerator, Marlborough Road, Wrexham Industrial Estate, Wrexham LL13 9RJ	
Location of the emission		A1	
Time and date of the emission		11:00- 11:29 18 th September 2015	
Substance(s) emitted	Media	Best estimate of the quantity or the rate of emission	Time during which the emission took place
HCL/ SO ²	Air	HCL 68.44 mg/m3/ SO2 238.9 mg/m3	11:00- 11:29
Measures taken, or Intended to be taken, to stop the emission		<ul style="list-style-type: none"> • Ceased charging waste • Investigation into source of waste being treated at the time • Inspection of abatement equipment to ensure working correctly 	

Part B

Any more accurate information on the matters for notification under Part A.	<p>The abatement system was checked and found to be operating normally.</p> <p>The cause of the breach has been attributed to the waste being processed at the time.</p> <p>The waste being processed at the time of the breach was investigated. The producer was identified. Although no specific problematic waste was identified.</p>
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Contact waste producer to try and identify source of waste.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission	No action applicable.

Name*	Stephen Blay
Post	SHEQ Officer
Signature	S Blay
Date	13 November 2015

• authorised to sign on behalf of Tradebe Healthcare National Limited