

NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION

Notification in accordance with PPC permit condition 5.1.1.6

Permit number:	WP3836ZF
Name of operator:	Tradebe Healthcare National Limited
Location of installation	Marlborough Rd, Wrexham Industrial Estate, Wrexham LL13 9RJ
Location of emission:	Release Point A2 – Incinerator Emergency Relief Vent
The emergency relief vent opened at:	21:10 – 21:17 25/1/2016 22:38 – 22:43 25/1/2016 02:23 -02:25 26/1/2016
Duration of operation:	7, 5 & 2 minutes respectively. 14 minutes in total
Reasons for operation:	ID fan tripping on thermal overload due to an inverter cooling fan failure
Measures taken to prevent a reoccurrence:	Replace the ID fan inverter cooling fan
The plant returned to normal operation at:	The plant will return to normal operation once the work to replace the cooling fan is completed

The loading of waste ceased while the emergency relief vent was open.

Notified by: Toby Hudson

Position: SHEQ Manager

Notification completed at: 15:30 on 26/1/2016