

Schedule 1 • Notification of abnormal emissions

Part A

|   |       |  |   |
|---|-------|--|---|
| Permit Number   |       | EPR/WP3836ZF   |   |
| Name of Operator  |       | Tradebe Healthcare National Ltd  |   |
| Location of Installation                                      |       | Wrexham Clinical Waste Incinerator, Marlborough Road, Wrexham Industrial Estate, Wrexham LL13 9RJ  |   |
| Location of the emission                                      |       | A1   |   |
| Time and date of the emission                                 |       | 18:30- 18:59 23 <sup>rd</sup> January 2016   |   |
| Substance(s) emitted  | Media | Best estimate of the quantity or the rate of emission  | Time during which the emission took place |
| SO <sub>2</sub>   | Air   | 231.44 mg/m <sup>3</sup>   | 18:30 -18:59                              |
| Measures taken, or Intended to be taken, to stop the emission |       | This was a very short lived event and the SO <sub>2</sub> concentration for the following ½ hour period, 19:00 - 19:29 was 26.15 mg/m <sup>3</sup> .<br>The lime abatement system was checked and confirmed as working correctly |   |

|           |                               |
|-----------|-------------------------------|
| Name*     | Toby Hudson                   |
| Post      | SHEQ Manager                  |
| Signature | T Hudson                      |
| Date      | 25 <sup>th</sup> January 2016 |

\* authorised to sign on behalf of Tradebe Healthcare National Limited