

## **NOTIFICATION OF EMERGENCY RELIEF VENT OPERATION**

Notification in accordance with PPC permit condition 5.1.1.6

Permit number:	WP3836ZF
Name of operator:	Tradebe Healthcare National Limited
Location of installation	Marlborough Rd, Wrexham Industrial Estate, Wrexham LL13 9RJ
Location of emission:	Release Point A2 – Incinerator Emergency Relief Vent
The emergency relief vent opened at:	10:30 08/05/2016
Duration of operation:	6 hour 01 minute
Reasons for operation:	Boiler Recirculation Fan Failure. Impeller became unattached from the motor shaft resulting in high temps that tripped the Emergency Vent.
Measures taken to prevent a reoccurrence:	Temporary repair carried out by Plant Maintenance Fitter and then RJW, (contractor) called to site to carryout permanent repair to the fan.
The plant returned to normal operation at:	17:15hrs

The loading of waste ceased while the emergency relief vent was open.

Notified by: Paul Phillips

Position: Plant Manager

Notification completed at: 16:00 09/5/2016