

RECEIVED

19 SEP 2013

HAF076v6 – 18.09.13

Schedule 6 - Notification**Part A**

Permit Number	PP3139GB
Name of Operator	Cory Environmental (Central) Limited
Location of Installation	Bangor Road Johnstown Wrexham LL14 6ET
Time and date of the detection	August 2013

b) Notification requirements for breach of a limit

To be notified within 24 hours of detection unless otherwise specified

Emission point reference/source	ID	Date	Leachate Head (m)	Transducer Reading (m)	Comments
Parameter(s)					
Limit					
Measured value and uncertainty					
Date and time of monitoring					
	HAF LC1	06/08/2013	14.76	0.10	perched
		13/08/2013	7.64	0.09	perched
		22/08/2013	6.76	0.05	perched
		29/08/2013	8.81	1.34	perched
	HAF LC3	06/08/2013	2.84	2.68	contractor visit
		13/08/2013	2.91	2.66	pump replaced
		22/08/2013	0.92	0.78	
		29/08/2013	0.56	0.43	
Measures taken, or intended to be taken, to stop the emission	See below.				

Part B

Any more accurate information on the matters for notification under Part A.	<p>The levels in LC1 have fluctuated between 14.76m and 6.76m during August. The transducer readings have been compliant throughout, but only at the depth the pump can be lowered to.</p> <p>A camera survey was undertaken on the 27th August and it was found that the two monitoring chambers LC1 and LC2 have damaged pipework which restricts the opening and is preventing the pumps going down to the base of the chamber. A separate email will be sent to NRW detailing what remedial measures are proposed.</p> <p>LC2 has been consistently below compliance levels throughout this reporting period.</p> <p>The levels in LC3 were 2.84m on the 6th August. The pump was checked and found to be working albeit at a slow flow rate. However, we have since replaced the pump and this has now brought the levels back under compliance.</p> <p>During August 1878 m3 of leachate was removed from site for treatment. 303 m3 of this was taken to Brookhill Landfill as part of a treatment trial.</p>
Measures taken, or intended to be taken, to prevent a recurrence of the incident	See above.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission	None – no pollution or harm has occurred.
The dates of any unauthorised emissions from the installation in the preceding 24	

OK FOR PUBLIC REGISTER

COPIED TO PUBLIC REGISTER

INITIALS

DATE

JB

20/9/13

JB

EORM

months.	
---------	--

Name*	Ian Craven
Post	NW Area Manager
Date	18/09/13

* authorised to sign on behalf of Cory Environmental (Central) Ltd

DATE	SIGNATURE	STAMP