

RECEIVED

HAF089 – 15.05.2014

15 MAY 2014

**Schedule 6 - Notification****Part A**

Permit Number	BS8621
Name of Operator	Cory Environmental (Central) Limited
Location of Installation	Bangor Road Johnstown Wrexham LL14 6ET
Time and date of the detection	Date entered onto Cory database

**b) Notification requirements for breach of a limit**

To be notified within 24 hours of detection unless otherwise specified

Emission point reference/source						
Parameter(s)	Date	Sample Point	Chloride (mg/l)		Sulphate (mg/l)	
Limit			Result	Limit	Result	Limit
Measured value and uncertainty						
Date and time of monitoring	08/04/2014	HAF SW2	100	67	240	224.3
Measures taken, or intended to be taken, to stop the emission	Please see below.					

**Part B**

Any more accurate information on the matters for notification under Part A.	Routine monitoring returned the elevated levels detailed above. All the other parameters remained within the SW limits set by the Permit. These breaches appear to be the result of rainfall over the area, causing a chalky substance from the clay to run down to the sump, which in turn is pumped to SW2.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Ditches will be excavated on site so as to divert past this seam in the clay. We expect this to solve the issue.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission	N/a
The dates of any unauthorised emissions from the installation in the preceding 24 months.	See previous Schedule 6 reports.

Name*	Anna Hamilton
Post	Environmental Data Assistant
Date	15/05/2014

\* authorised to sign on behalf of Cory Environmental (Central) Ltd

