

Schedule 5 Notification

PART A

Permit Number:	BR9715B
Name of Operator:	Solutia UK Ltd
Location of Installation:	Corporation Road, Newport, Gwent, NP194XF
Location of the emission:	Site Effluent Pipeline
Time and date of the emission:	17/07/22 AM

Substance(s) emitted	Media e.g. air /water	Best estimate of the quantity or the rate of emission	Time during which the emission took place
Treated Effluent	Estuary	Pipeline leak Unquantified pending investigation	Notification date through to repair

Description of the failure or accident, and... Measures taken, or intended to be taken, to stop the emission:	A disturbance of the sea-water surface near the Solutia effluent pipeline was brought to Eastman's attention on the specified date. Subsequent observations found this to be in the location of a previous pipeline repair, indicating that the repair had likely partially failed Efforts were already underway to 'slip-line' the effluent pipe (installing a new pipe within the existing line) however various constraints mean that this is a number of weeks off In the meantime, investigation & assessment will be undertaken to determine whether; the leak might be tolerable for a duration until the slip-lining can occur, or whether the area will need to be excavated in order to attempt a further temporary repair (access permissions to be sought in the meantime). In addition minimal pump-rates will be adopted to limit any avoidable stresses on the pipeline Further information on the; extent & nature of the integrity failure to follow in the Part B follow-up
--	---

* Signed:



Date: 18/07/2022

* authorised to sign on behalf of Solutia UK Ltd