

## **Biffa Cardiff WMRC – Report into Activities 2022**

### **A) Review of Monitoring**

Emission monitoring of pH at point source (S1) discharge to sewer – see attached form.

### **B) Production/ Treatment data**

Hazardous waste inputs 2022 – 1978.25 Tonnes

Hazardous waste treated 2022 – 0 Tonnes

Non Hazardous waste inputs 2022 – 902.6 Tonnes

### **C) Performance Parameters S5.3**

Downtime of pH Probe – 0 days inoperative. See attached form

### **D) Details of any contamination or decontamination of the site which has occurred.**

None