

Schedule 6 - Notification

This page outlines the information that the Operator must provide.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the PPC Regulations.

Part A

Permit Number	CP3735PB
Name of Operator	CWM Environmental Limited
Location of Installation	Nantycaws Landfill Site, Llanddarog Road, Nantycaws, Carmarthen, SA32 8BG
Time and date of the detection	13/02/2023

(a) Notification requirements for any malfunction, breakdown or failure of equipment or techniques, accident, or fugitive emission which has caused, is causing or may cause significant pollution	
To be notified within 24 hours of detection	
Date and Time of the event	
Reference or description of the location of the event	
Description of where any release into the environment took place	
Substances(s) potentially released	
Best estimate of the quantity or rate of release of substances	
Measures take, or intended to be taken, to stop any emission	
Description of the failure or Accident	

(b) Notification requirements for the breach of a limit	
To be notified within 24 hours of detection unless otherwise specified below	
Emission point reference/source	UD4
Parameter(s)	Mecoprop (MCP)
Limit (µg/l)	0.055
Measured value and uncertainty (µg/l)	0.0688
Date and time of monitoring	11/01/2023 (incomplete analysis received 13/02/2023) Note that delays from the laboratory for the quarterly results of analysis have occurred and, on this basis an incomplete analysis has been provided and screened to date. Outstanding results will be provided mid-February 2023.
Measures taken, or intended to be taken, to stop the emission	MCP exceedances also occurred at BH3/5, UD1 and NACW203. A CAR Notice was received on 8th February 2023 and a review of MCP trends are currently being investigated for the site in response

	to this notice and as recommended in the sites annual report (2022).
--	--

Time periods for notification following detection of a breach of a limit	
Parameter	Notification period
MCP	24hours

(c) Notification requirements for the detection of any significant adverse environmental effect	
To be notified within 24 hours of detection	
Description of where the effect on the environment was detected	
Substances(s) detected	
Concentrations of substances detected	
Date of monitoring/sampling	

Part B to be supplied as soon as practicable

Any more accurate information on the matters for notification under Part A	
Measures taken, or intended to be taken, to prevent a recurrence of the incident	
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	No Schedule 6 Notices have been issued for MCP exceedances at UD4 within the last 24 months. Groundwater location NACW228 exceeded MCP in August 2021, January 2022 and October 2022. Cell 1/2 (leachate monitoring location) exceeded MCP in January 2021, October 2021 and October 2022. Schedule 6 Notices have been issued for these locations. A CAR Notice was received on 8th February 2023 and a review of MCP trends are currently being investigated for the site in response to this notice and as recommended in the sites annual report (2022). Continued surveillance of MCP concentrations in successive monitoring rounds, including UD and surface water.
The dates of any unauthorised emissions from the installation in the preceding 24 months	No previous emissions at UD4 in past 24 months.

Name*	Melanie Cross
Post	Environmental Consultant
Signature	
Date	14/02/2023

* authorised to sign on behalf of Cwm Environmental Ltd