

Rosina weir

Photo survey for NRW impoundment license

West Wales Rivers Trust




Figure 0. Locations of photos taken during the surveys – numbers relate to photo figures below.



Figure 1. SN 62116 10747 View facing DS from RHB.



Figure 2. SN 62104 10742 Channel facing US from RHB. Island, channel remains tree lined.



Figure 3. SN 62114 10744 Channel facing US from RHB.



Figure 4. SN 62114 10741 Channel facing DS from LHB.



Figure 5. SN 620110 10723 Channel facing DS from RHB.



Figure 6. SN 62107 10729 Example bank type - RHB.



Figure 7. SN 62133 10704 RHB vegetated and heavily tree lined. Taken from RHB facing DS.



Figure 8. SN 62134 10721 US weir banks vegetated and tree lined. Taken from RHB facing US.



Figure 9. SN 62148 10699 RHB above weir. Taken from RHB facing DS.



Figure 10. SN 62160 10695 LHB above weir, taken from RHB.



Figure 11. SN 62158 10698 Immediately US weir taken from RHB facing US.



Figure 12. SN 62163 10689 Weir from RHB.



Figure 13. SN 62163 10690 DS weir from RHB.



Figure 14. SN 62163 10669 Erosion DS of weir. Taken facing US from RHB.



Figure 15. SN 62167 10686 DS weir facing US from RHB.



Figure 16. SN 62168 10677 LHB taken from RHB.



Figure 17. SN 62172 10684 Weir from DS facing US on RHB.



Figure 18. SN 62174 10686 LHB DS of weir, taken from RHB.



Figure 19. SN 62174 10686 RHB DS of weir, taken from RHB.



Figure 20. SN 62191 10672 Channel facing US from RHB.



Figure 21. SN 62198 10669 Channel facing DS from RHB.



Figure 22. SN 62218 10635 Channel facing DS. River Amman enters on LHB DS in photo with weir at confluence.

Photo taken from RHB.



Figure 23. SN 62221 10595 Channel taken from RHB, confluence with Amman.



Figure 24. SN 62210 10585 Channel taken from RHB facing DS.