

SCHEDULE 5 Notification**Part A**

Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	21/02/2022

(b) Notification requirements for breach of a permit condition

Emission point/reference source	W1 Long Sea Outfall																
Parameter(s)	Sulphides																
Limit	0.1 mg/l																
Measured value and uncertainty	0.12 mg/l 0.01 mg/l uncertainty of measurement based on a measured value of 0.1 mg/l.																
Date and time of monitoring	Weekly average permit breach in calendar week 7: 13/02/2022 – 19/02/2022.																
Measures taken, or intended to be taken, to stop the emission	Investigations are ongoing as to the cause of the breach. The breach is a result of one day of elevated sulphides on the 18 th February – subsequent daily composite samples have been under the permitted limit. <table><tr><td>13/02/2022</td><td>0.043 ppm</td></tr><tr><td>14/02/2022</td><td>0.042 ppm</td></tr><tr><td>15/02/2022</td><td>0.059 ppm</td></tr><tr><td>16/02/2022</td><td>0.039 ppm</td></tr><tr><td>17/02/2022</td><td>0.088 ppm</td></tr><tr><td>18/02/2022</td><td>0.448 ppm</td></tr><tr><td>19/02/2022</td><td>0.09 ppm</td></tr><tr><td>20/02/2022</td><td>0.08 ppm</td></tr></table>	13/02/2022	0.043 ppm	14/02/2022	0.042 ppm	15/02/2022	0.059 ppm	16/02/2022	0.039 ppm	17/02/2022	0.088 ppm	18/02/2022	0.448 ppm	19/02/2022	0.09 ppm	20/02/2022	0.08 ppm
13/02/2022	0.043 ppm																
14/02/2022	0.042 ppm																
15/02/2022	0.059 ppm																
16/02/2022	0.039 ppm																
17/02/2022	0.088 ppm																
18/02/2022	0.448 ppm																
19/02/2022	0.09 ppm																
20/02/2022	0.08 ppm																

REF: S5N/22/12A