

SCHEDULE 5 Notification	
Part A	
Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	08:00 7 th March 2022

(a) Notification requirements for any activity that gives rise to an incident or accident which significantly effects or may significantly affect the environment	
Date and time of the event	10:00 4 th March to 08:00 7 th March 2022
Reference or description of the location of the event	A1 Sinter Main Stack SO ₂ and NO _x Monitor Failure
Description of where any release into the environment took place	Monitor failure: 04/03/2022 05/03/2022 06/03/2022 07/03/2022 Data restored 08:00 7 th March
Substance(s) potentially released	SO ₂ and NO _x
Best estimate of the quantity or rate of release of substance(s)	N/A
Measures taken, or intended to be taken, to stop the emission	Investigation is ongoing.
Description of the failure or accident	Failure to continuously monitor SO ₂ and NO _x at A1 Sinter Main Stack between 10:00 4 th March and 08:00 7 th March.
REF: S5N/22/19A	