

### SCHEDULE 5 Notification

**Part A**

Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	09/05/2022: 8.00am

**(b) Notification requirements for breach of a permit condition**

Emission point/reference source	W1 Long Sea Outfall
Parameter(s)	Thiocyanate
Limit	4 mg/l
Measured value and uncertainty	Measured value: 6.35 mg/l Monitoring uncertainty value = 0.4 mg/l based on a measured value of 4 mg/l.
Date time of monitoring, and emission value.	Date time of monitoring = 09/05/22 Adjusted result following the application of uncertainty = 5.95 mg/l.
Measures taken, or intended to be taken, to stop the emission	Investigations are ongoing as to the cause of the breach.
<b>REF: S5N/22/40A</b>	