

SCHEDULE 5 Notification	
Part A	
Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	16/05/2022; 8:00am

(b) Notification requirements for breach of a permit condition	
Emission point/reference source	W1 Long Sea Outfall
Parameter(s)	Cyanide
Limit	0.1 mg/l
Measured value and uncertainty	Measured value: 0.12 mg/l. Monitoring uncertainty value = 0.01 mg/l based on a measured value of 0.1 mg/l.
Date time of monitoring, and emission value.	Date time of monitoring = 08/05/2022 – 14/05/2022 Adjusted result following the application of uncertainty = 0.11 mg/l.
Measures taken, or intended to be taken, to stop the emission	Investigations are ongoing as to the cause of the breach.
REF: S5N/22/43A	