

SCHEDULE 5 Notification**Part A**

Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	18/07/2022; 8:00am

(b) Notification requirements for breach of a permit condition

Emission point/reference source	W1 Long Sea Outfall
Parameter(s)	Thiocyanate
Limit	4 mg/l
Measured value and uncertainty	Measured value: 4.79 mg/l Monitoring uncertainty value = 0.4 mg/l based on a measured value of 4 mg/l.
Date time of monitoring, and emission value.	Calendar week 28: 10/07/2022 – 16/07/2022. Adjusted result following the application of uncertainty = 4.39 mg/l.
Measures taken, or intended to be taken, to stop the emission	Investigations are ongoing as to the cause of the failure.

REF: S5N/22/56A