

SCHEDULE 5 Notification	
Part A	
Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	12/06/2023; 8:30am

(b) Notification requirements for breach of a permit condition	
Emission point/reference source	W1 Long Sea Outfall
Parameter(s)	Total volume of discharge flow
Limit	6000m3/hr
Measured value and uncertainty	Continuous flow meter on the W1 permit point has lost data from 22:00 on 10/06/2023 until 08:00 12/06/2023.
Date time of monitoring, and emission value.	Data before shows the flow meter working before the lapse in performance: 09/06/2023 average 1463.42 m3/hr 10/06/2023 average 1307.80 m3/hr 11/06/2023 average 0.00 m3/hr 12/06/2023 average 700.81m3/hr 13/06/2023 average 1004.70m3/hr Max 09/06/2023 – 13/06/23 : 2208.29 m3/hr Average 09/06/2023 – 13/06/23 : 883.19m3/hr Lost 32hours of flow from 22:00 10th June until 08:00 12th June 2023
Measures taken, or intended to be taken, to stop the emission	Flow meter is part of the ECE list and tracked and reviewed daily to ensure its operation. Flow meter resumed flow data 08:00 12th June 2023 Investigations are ongoing as to the cause of this lost data.
REF: S5N/23/33A	