

SCHEDULE 5 Notification	
Part A	
Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	25/06/2023

(b) Notification requirements for breach of a permit condition	
Emission point/reference source	Sinter A1 main SO ₂ monitor
Parameter(s)	SO ₂ continuous measurement
Limit	500mg/m ³
Measured value and uncertainty	24/06/2023 – 600.15mg/m ³ 25/06/2023 – 596.71mg/m ³
Date and time of monitoring	24 th and 25 th of June 2023
Measures taken, or intended to be taken, to stop the emission	A fault was found with the monitor as it had been reporting waste gas SO₂ levels in excess of the 500mg/m³ whilst the Sinter Plant was offline. The figures listed below were recorded for when the Sinter Plant was offline. 21/06/2023 – 716.86mg/m³ 22/06/2023 – 688.49mg/m³ 23/06/2023 – 600.48mg/m³ The Sinter Plant was returned to operation on the 24th of June however, the fault with the monitor persisted. This was rectified on the 26th of June following a replacement of a lamp within the monitor and SO₂ levels returned to below the limit.
REF: S5N/23/36A	