

SCHEDULE 5 Notification	
Part A	
Permit Number:	BL7108IM
Name of Operator:	Tata Steel UK Ltd
Location of Facility:	Port Talbot Works
Time & Date of the Detection	30/08/2023 @ 08:00

(a) Notification requirements for any activity that gives rise to an incident or accident which significantly effects or may significantly affect the environment	
Date and time of the event	25/08/2023 @ 11:30 – 29/08/2023 @ 18:30
Reference or description of the location of the event	A1 Sinter Main Stack SO ₂ and NO _x Monitor Failure
Description of where any release into the environment took place	Monitor failure: 25/08/2023 26/08/2023 27/08/2023 28/08/2023 29/08/2023 Data restored 29/08/2023 @ 18:30
Substance(s) potentially released	SO ₂ and NO _x
Best estimate of the quantity or rate of release of substance(s)	N/A
Measures taken, or intended to be taken, to stop the emission	Investigation is ongoing.
Description of the failure or accident	Failure to continuously monitor SO ₂ and NO _x at A1 Sinter Main Stack between 11:30 25/08/2023 and 18:30 29/08/2023.
REF: S5N/23/47A	