

Schedule 1 - Notification of abnormal emissions

This page outlines the information that the Operator must provide to satisfy conditions 5.1.1 and 5.1.2 of this Permit.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the PPC Regulations.

Part A

Permit Number	<i>BX3376IG</i>
Name of Operator	<i>Continental Teves,</i>
Location of Installation	<i>Ebbw Vale</i>
Location of the emission	<i>Sump for floor cleaning waste adjacent to effluent treatment plant</i>
Time and date of the emission	<i>23/01/23 – 12.00 approximately</i>

Substance(s) emitted	Media	Best estimate of the quantity or the rate of emission	Time during which the emission took place
<i>Soluble Oil @ 6%</i>	<i>Machining Coolant</i>	Approximately 800 litres	Approximately between 12.00 to 13.00

Measures taken, or intended to be taken, to stop the emission	Emission was completely discharged before it was reported to relevant Continental personnel.
---	--

Part B

Any more accurate information on the matters for notification under Part A.	Following a leak of coolant (soluble oil) on a CNC cutting machine, the coolant was collected in a floor cleaning machine by the cleaning contractors. Instead of disposing of the waste into the waste oil storage tank they disposed of it into the sump that discharges into the effluent treatment discharge pipework which goes to the foul sewer which is controlled by an IPPC permit and a consent to discharge.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	- Conduct awareness training of Continental's Spill Control procedures (cleaning staff, supervisors and Emergency response Team) - Replace previous signage with a new, more explicit sign

	3. Review training procedures for both Continental and contractors/service providers See attached 8D report
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission	
The dates of any unauthorised emissions from the installation in the preceding 24 months.	N/A

Name*	Philip French
Post	Head of Plating and Environmental Management
Signature	<i>P. French</i>
Date	03.02.2023

* Authorised to sign on behalf of Continental Teves UK Limited