

**CRYMLYN BURROWS MATERIALS RECOVERY AND ENERGY CENTRE**  
**ENVIRONMENTAL PERMIT VARIATION AND PARTIAL SURRENDER APPLICATION**  
**CONTENTS PAGE**

Neath Port Talbot County Borough Council  
November 2023

SLR Ref No: 402.02718.00005

## **Section 1**

### **Non-Technical Summary (NTS)**

## **Section 2**

### **Application Forms – Part A, C2, C3, C4, E2, and F1**

- WAMITAB Certificates
- Appendix A\_ Table 1a Continued
- Current OPRA Spreadsheet

## **Section 3**

### **Working Plan (all appendices to be included once approval has been gained for the variation and partial surrender)**

- Appendix 01 Environmental Permit (TBC)
- Appendix 02 WAMITAB Certificates
- Appendix 03 Emergency Contacts
- Appendix 04 Fire Prevention and Mitigation Plan (TBC)
- Appendix 05 Odour Management Plan (TBC)
- Appendix 06 Pest Management Plan (TBC)

## **Section 4**

### **Environmental Risk Assessment**

- Appendix 001 Envirocheck Report, Dated 13<sup>th</sup> August 2021

## **Section 5**

### **Odour Management Plan**

## **Section 6**

### **Fire Prevention and Mitigation Plan**

## **Section 7**

### **Pest Management Plan**

## **Section 8**

### **Site Condition Report**

- Appendix SCR1: Ground Conditions and Contamination Study (Gibb 1998)
- Appendix SCR2: Table 1.1.1, Permit BJ5775 issued May 2002

**CRYMLYN BURROWS MATERIALS RECOVERY AND ENERGY CENTRE**  
**ENVIRONMENTAL PERMIT VARIATION AND PARTIAL SURRENDER APPLICATION**  
**CONTENTS PAGE**

Neath Port Talbot County Borough Council  
November 2023

SLR Ref No: 402.02718.00005

- Appendix SCR3.1 Quantum 2010 Planning GI recycling Building Phase I Investigation
- Appendix SCR3.2 Quantum 2010 Planning GI recycling Building Phase II Investigation
- Appendix SCR3.3 Jacob 2012 Site Investigation Factual Report
- Appendix SCR3.4 Jacob 2012 MREC Site Investigation Interpretive Report
- Appendix SCR3.5 WYG 2018 A107290 Crymlyn Burrows Interpretive Report
- Appendix SCR3.6 SLR 2023 230616\_402.V02718.00005.00007\_Crymlyn\_Burrows\_SI\_Report.v3
- Appendix SCR3.7: CAR\_NRW0042762
- Appendix SCR4: Envirocheck Report, Dated 13<sup>th</sup> August 2021
- Appendix SCR5: W1 Surface Water Monitoring Results 2019 – 2023

## **Section 9**

### **Drawings**

- Drawing 01 Environmental Site Setting Local Receptors
- Drawing 02 Environmental Site Setting Natural and Cultural Heritage
- Drawing 03 Environmental Permit Boundary and Site Layout
- Drawing 031 Transfer Station Proposed Layout Sheet 1
- Drawing 032 Transfer Station Proposed Layout Sheet 2
- Drawing 033 Transfer Station Proposed Layout Sheet 3
- Drawing 070 Transfer Station Site Drainage Layout Sheet 1
- Drawing 071 Transfer Station Site Drainage Layout Sheet 2