

Schedule 5 Notification

PART A

Permit Number:	BR9715B
Name of Operator:	Solutia UK Ltd
Location of Installation:	Corporation Road, Newport, Gwent, NP194XF
Location of the emission:	'W1' Effluent Pipeline
Time and date of the emission:	29/08/2023 ~0900

Substance(s) emitted	Media e.g. air /water	Best estimate of the quantity or the rate of emission	Time during which the emission took place
Site effluent	Liquid discharge	Leak estimated at <100 l/h (whilst pumping operational)	Leading up to 29/08/2023

Description of the failure or accident, and... Measures taken, or intended to be taken, to stop the emission:	A leak was noted on the site main effluent recirculation pipeline (above ground) which is situated near the main effluent pump house. The leak is from a pinhole, the rate of the leak has been estimated as <100 l/hr worst case when the effluent is on recirculation. When the effluent is on discharge, the leak reduces to drips. Until the leak is fixed, the effluent pump is being stopped between effluent discharges (recirculation is not being used). A temporary repair has been implemented to reduce the leak to a smaller amount. Physical & planning preparations have been made such that a repair can be affected at the first possible opportunity. Material availability may mean that the leak is not fixed until Thursday 31st August.
--	---

* Signed: 

Date: 29/08/2023

* authorised to sign on behalf of Solutia UK Ltd