



STRUCTURAL ENGINEERING : PROJECT MANAGEMENT

Photo Survey Report  
Parc Coed y Nant  
Cardiff  
CF23 7EZ

## **Index**

1.0 Photos 2019

2.0 Photos 2023

## 1.0 Photograph Sheets 2019



Wall from left hand side of Dam



Wall from right hand side of Dam





Sunken side slab



Degree of settlement to slab





Water holding at pond edge



Overtopping of Dam wall



## 2.0 Photograph Sheets 2023



Repaired dam coping stones and barrier





Uncharted manhole exposed during works





